


Copycat Hand




Scroll for
building
instructions








7




Make sure all motors stay
at their zero position while
building this model.












11





7





(5 x)
























(2 x)






11









15



15



11



7



11



7



(12 x)




(8 x)







15




15














3





3

















3





3





























B = Top Input Motor
D = Bottom Input Motor




A = Top Output Motor
C = Bottom Output Motor





3





(5 x)





(6 x)











































5



(9 x)



